




1a
TOP VIEW



1b
SIDEVIEW



APPL #
10/796,538



2a
SIDE VIEW

TREKKING POLE RECEIVER LEGS
(POLE TIP) (END LEGS)

2b
FRONT VIEW
(90° FROM SIDE VIEW)


2 of 5

2

APPL # 10/796, 538

BEST AVAILABLE COPY


36 FRONTVIEW 90°
TURN FROM FRONTVIEW



TREKING POLE RECEIVER LEGS
(POLE HANDLE RECEIVER)
(END LEGS)

3A SIDEVIEW


SIDE RAIL
RECEIVER
HOLE




(3)

46
FRONTVIEW
90° TURN FROM
SIDEVIEW

ICE AX POINT RECEIVER LEGS



49 SIDEVIEW




4 of 5

APPL # 101796,538

56 FRONTVIEW
90° TURN FROM SIDEVIEW

ICE AX SHAFT RECEIVER LEG



5a SIDEVIEW

